

Note: For the built—in bathtub with electric appliance, the platform should have air vent, overflow port and safety exit(please refer to the attached installation statement). Drain pipe and the floor drain should be sealed, (Please refer to the attached installation statement). If did not do as requested, that means the product did not fixed correctly, the manufacturer will not offer after sales service!